

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

09/19/2019

Submitted Date:

09/25/2019

Document Number:

696300619**FIELD INSPECTION FORM**
 Loc ID 318901 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:           
**Operator Information:**OGCC Operator Number: 49407Name of Operator: KUGLER\* DEAN & JOE DBA D-J OIL COMPANYAddress: P O BOX 72City: NEW RAYMER State: CO Zip: 80742**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**14 Number of Comments9 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		dakugler@yahoo.com	
Sutphin, Dirk		dirk.sutphin@state.co.us	
Kugler, Dean		dlkug@yahoo.com	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242412	WELL	SI	11/01/2015	OW	123-10203	COLORADO FEDERAL 1	PA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate, sign now has the 24 hour Emergency Contact info posted.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash on the north west side and east side of pumpinig unit, see photos		
Corrective Action:	Comply with Rule 603.f .	Date:	10/25/2019
Type	DEBRIS		
Comment:	Debris inside the engine shed, see photos		
Corrective Action:	Comply with Rule 603.f .	Date:	10/25/2019
Type	WEEDS		
Comment:	Weeds are actively growing on the entire location. See photos		
Corrective Action:	Comply with Rule 603.f .	Date:	10/09/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Unused equipment		

Corrective Action:	Comply with Rule 603.f .		Date:	11/25/2019
Type: Pump Jack	# 1			
Comment:	Unused Equipment			
Corrective Action:	Comply with Rule 603.f .		Date:	11/25/2019
Type: Other	# 1			
Comment:	Well bore, well bore is open to atmosphere, please cut and cap or install Nightcap to open casing			
Corrective Action:	Comply with Rule 605.c.		Date:	10/04/2019
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:	Unused Equipment			
Corrective Action:	Comply with Rule 603.f .		Date:	11/25/2019

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Unused equipment				
Corrective Action:	Comply with Rule 603.f .				Date: 11/25/2019

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		40.630330,-103.851220
Comment:	Unused Equipment				
Corrective Action:	Comply with Rule 603.f .				
	Date: 11/25/2019				

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 242412 Type: WELL API Number: 123-10203 Status: SI Insp. Status: PA

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 09/19/2019 at approximately 11:06, I, Inspector Erica Petrie, conducted a Field Inspection at Kugler* Dean and Joe DBD D-J Oil Company, Colorado Federal #1 at Location #318901 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>An open Well Bore, it appears that the Well has been recently Plugged and left with a well bore open to atmosphere. Well needs to have a Nightcap installed or cut and capped, see photo 8. Comply with Rule 605.c. Corrective Action Date 10/04/2019.</p> <p>Unused equipment and Debris in the Engine Shed, see photo 6 &amp; 7. Comply with Rule 603.f. Corrective Action Date 10/25/2019.</p> <p>Trash on the Northwest and East sides of Pumping Unit, see photos 1 &amp; 5. Comply with Rule 603.f. Corrective Action Date 10/25/2019.</p> <p>Weeds are actively growing on the entire location, see photos. Comply with Rule 603.f. Corrective Action Date 10/09/2019.</p> <p>Multiple Unused Equipment: Separator, Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, Crude Oil Tanks (2), Produced Water Tanks. Comply with Rule 603.f. Corrective Action Date 11/25/2019.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Educational Inspections</p>	petrie	09/25/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402188447	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946714">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946714</a>
696300625	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946680">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4946680</a>