

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2019

Submitted Date:

10/01/2019

Document Number:

679601674**FIELD INSPECTION FORM**
 Loc ID 332500 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273597	WELL	SI	04/01/2017	OW	123-22384	THAYER 19-34	TA

General Comment:

Location				
Lease Road:				
Type	Access			
comment:	In Crop			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Adequate			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment at wellhead. See attached photo.			
Corrective Action:	Comply with Rule 603.f.			Date: 04/04/2019
Type	WEEDS			
Comment:	Weeds inside fencing. See attached photo.			
Corrective Action:	Comply with Rule 603.f.			Date: 10/11/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Panel			
Corrective Action:				Date:
Equipment:				
Type: Plunger Lift	# 1			corrective date
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 273597 Type: WELL API Number: 123-22384 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTEDComment: TA; MIT requirement waived per variance doc#401474555.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>THIS IS A FOLLOW UP INSPECTION TO DOC#: 696100357. ORANGE DECOMISSION TAG HAS BEEN APPLIED TO WELLHEAD, BUT UNUSED EQUIPMENT STILL REMAINS INSIDE FENCING THAT CONTAINS WELLHEAD. ONE NEW CORRECTIVE ACTION HAS BEEN ASSIGNED TO THIS LOCATION AS WELL. PLEASE SEE ALL ATTACHED PHOTOS.</p> <p>On Tuesday, October 1, 2019 at approximately 9:45, I, Inspector Brittani Santistevan, conducted an on-site inspection at THAYER 19-34 (Noble Energy), at location #: 332500 in WELD COUNTY Colorado.</p> <p>While there, I observed a temporarily abandoned wellhead.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Weeds inside fencing that contains wellhead. COMPLY WITH RULE 603.F. (Corrective Action Date: October 11, 2019) See attached photo #2.</p> <p>2. Unused equipment inside fencing. COMPLY WITH RULE 603.F. (Corrective Action Date: April 4, 2019) See attached photo #3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	10/01/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601675	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4952362