

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2019

Submitted Date:

10/02/2019

Document Number:

693501492

FIELD INSPECTION FORM

Loc ID 455317 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Carlisle, J	970-534-6006	COGCCInspections@extracti onog.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455315	WELL	DG	06/10/2019		014-20757	Livingston S19-25-14C	DG

General Comment:

Inspected Facilities

Facility ID: 455315 Type: WELL API Number: 014-20757 Status: DG Insp. Status: DG

Complaint

Comment: Inspection in response to complaint.
 Field Inspector Assigned: Randy Silver
 Complaint Received
 Date: 09-30-2019
 Complaint Contacted:
 Date: 09-30-2019 Time: 7:43AM via phone
 Location ID #455317
 Inspection Document # 693501484
 Complaint Document #200448162
 Nature of Complaint: Ligiting
 Field Inspector Actions:
 On 09-30-2019, I Randy Silver area field inspector was assigned a complaint received by COGCC staff in reference to Lighting. The complainant Ed Young Broomfield stated the issues were on the Livingston drilling rig.
 On 09-30-2019, I attempted to make contact with the complainant who indicated that on 9-29-19 he observed the lights on the drilling rig failed around 9:30 PM they did come back on.
 I performed a complete site inspection of the oil and gas location and associated wells in the area. At time of inspection, derrick lights were operational.
 At time of inspection, I spoke with Manny Parras drilling supervisor he stated at time of complaint they did have an issue with the derrick lights they called electrician and light were repaired shortly after.
 Weather conditions: Cloudy and location wet
 See inspection document #693501484 per my inspection.
 No violation of COGCC rules were observed at the time of the inspection.
 All information reviewed and site inspection information were submitted to the COGCC for further review.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
See Doc #693501484 for full inspection	silverr	10/02/2019