

Inspection Photos
Operator: BP America
Location/API #: 067-07175
Date: 9-30-2019



Photo 1 View of the fill slope in the eastern project area from the northeastern corner facing southward. Revegetation is comprised of smooth brome and western wheatgrass, with young ponderosa pine trees.



Photo 2. View of oily material on well pad surface. Liquid observed on soil surface. This material is a potential stormwater pollutant.



Photo 3. View of reference area vegetation, comprised of ponderosa pine forest with gambel oak and herbaceous understory.