

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/02/2019

Submitted Date:

10/02/2019

Document Number:

699300305

FIELD INSPECTION FORM

Loc ID 336337 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294580	WELL	PR	07/01/2018	GW	123-25501	RAY NELSON 13-32	PR
294594	WELL	SI	12/01/2018	GW	123-25514	RAY NELSON 24-32	SI
294595	WELL	PR	07/01/2018	GW	123-25515	RAY NELSON 14-32	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	Chain link topped with barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chain link topped with barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chain link topped with barbwire		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	all wells appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:	Automation		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	150bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	330 bbl	

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Share contianment with produced water tank				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 294580 Type: WELL API Number: 123-25501 Status: PR Insp. Status: PR

Producing Well

Comment:	<u>PR</u>	
Corrective Action:		Date:

Facility ID: 294594 Type: WELL API Number: 123-25514 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:	<u>SI</u>	
Corrective Action:		Date: _____

Facility ID: 294595 Type: WELL API Number: 123-25515 Status: PR Insp. Status: PR

Producing Well

Comment:	<u>PR</u>	
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/2/2019 at approximately 1030 hrs. Inspector Robbie Revas, Conducted an on-site inspection at the Roy Nelson 14-32 Crestone Peak Resources at API #05-123-25515 in Weld County Colorado. While there, I observed a Producing wellsite and Nelson E 1 Battery. This is a follow up inspection per Doc. # 688401919. During this inspection the following compliance issues appear to have been addressed: Rule 603.f: Unused equip. See photo #4. Rule 605.d: Well appears to be leaking. See photo #6. Rule 603.f: Unused unmarked risers no LOTO See photos #4, 7, 8, 9 and 10. Rule 907.e: Stained soil around WH. See photos #5 and 6. Location is wet, weather is cloudy. No follow up on this site inspection needs to be conducted. Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	10/02/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300306	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4953766