

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2019

Submitted Date:

09/26/2019

Document Number:

699500148

**FIELD INSPECTION FORM**

Loc ID 320166 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10548  
Name of Operator: HRM RESOURCES II LLC  
Address: 410 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

- 7 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		jeremy@p3petro.com	
		fbair@p3petro.com	
Burn, Diana		diana.burn@state.co.us	
,		dnr_cogccengineering@state.co.us	
		jh@p3petro.com	
,		dnr_cogccenforcement@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202876	WELL	SI	10/01/2017	OW	001-08281	CRYSTAL-HUBBS 1	SI

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	no signage on wellhead		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	10/26/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	mechanical issue in separator house see pic 5,6		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/26/2019
Type	OTHER		
Comment:	stained soil in separator house see pic 5,6		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e	Date:	10/26/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	fabricated fencing around wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		39.949330,-104.423590
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES	
Comment:	Wellhead appears to be venting gas, odors present at wellhead see pic 3, and video	
Corrective Action:	Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.	Date: 09/26/2019

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 202876 Type: WELL API Number: 001-08281 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Comment: <input style="width: 90%;" type="text"/> Corrective Action: <input style="width: 90%;" type="text"/>						Date: _____
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On 9/26/19 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at P3 Petroleum- API 001-08281 – Crystal Hubbs 1 in Adams County Colorado. While there, I observed Shut in well                      This is a follow up inspection from document # 688400370 Corrective Actions are Delinquent                      During this inspection the following possible compliance issues were observed:                      no signage on wellhead                      Install sign to comply with Rule 210.b.10/26/19                      stained soil in separator house see pic 5,6                      Properly treat or dispose of oily waste in accordance with 907.e 10/26/19                      mechanical issue in separator house see pic 5,6                      Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 10/26/19                      Wellhead appears to be venting gas odors present at wellhead see pic 3, and video                      Contact the COGCC Area Engineer for next steps per Rule 912.b. Refer to the venting and flaring NTO for further details.9/26/19</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	medinaj	09/26/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402190329	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948190">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948190</a>
699500149	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948171">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948171</a>
699500150	venting video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948172">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4948172</a>