

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [Chain link topped with barbwire](#)

Corrective Action:

Date:

Type SEPARATOR

Comment: [Chain link topped with barbwire](#)

Corrective Action:

Date:

Type TANK BATTERY

Comment: [Chain link topped with barbwire](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

5

Comment: [Automation](#)

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

2

Comment:

Corrective Action:

Date:

Type: Bradenhead

1

Comment: [Appears to be plumbed to surface](#)

Corrective Action:

Date:

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	Share containment with crude oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	5	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	315 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 247004 Type: WELL API Number: 123-14801 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/3/19 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Baldwin Robert E Unit #2 Kerr McGee, at API #05-123-14801 in Weld County Colorado. While there, I observed SI wellsite and Tank Battery. Lease operator some maintenance work going on at the site for flow lines, and was fenced off with orange construction fence. During this inspection no compliance issues were observed: Location photos attached. Location is dry, weather is clear/cloudy. No follow up on this site inspection needs to be conducted. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	10/03/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300310	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4954635