

Inspection Photos
Location Name: BROWN-66N63W /2SENW
Location #: 306163



Photo #1
Brown 22-2 (05-123-24094) Wellsite
Temporarily Abandoned | TA
prior insp.



Photo #2
Brown 22-2 Wellsite
Shut-In | SI

Inspection Photos
Location Name: BROWN-66N63W /2SENW
Location #: 306163



Photo #3
Brown 22-2 Battery
Shut-down | Inactive
prior insp.



Photo #4
Brown 22-2 Battery
Shut-down | Inactive

Inspection Photos
Location Name: BROWN-66N63W /2SENW
Location #: 306163



Photo #5
Brown 22-2 Battery
NE Corner – Stormwater erosion
prior insp.



Photo #6
Brown 22-2 Battery
NE Corner – Stormwater erosion
NOW Appears mitigated

Inspection Photos

Location Name: BROWN-66N63W /2SENW

Location #: 306163



Photo #7

Brown 22-2 Well access road
NE Corner – Stormwater rutting
prior insp.



Photo #8

Brown 22-2 Battery
NE Corner – Stormwater rutting
NOW Appears mitigated

