

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2019

Submitted Date:

10/03/2019

Document Number:

696101361

**FIELD INSPECTION FORM**

Loc ID 306163 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

18 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285951	WELL	SI	03/01/2019	OW	123-24094	BROWN 22-2	SI

**General Comment:**

This is a WELL & BATTERY inspection.  
Well: Shut-In | SI.  
Battery: Shut-down | Inactive.  
  
[Follow-up to Field Inspection Report Doc. #684905421 dated 05/11/2018.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>		Date: _____

<b>Good Housekeeping:</b>			
Type			
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Iron pipe		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Iron panel		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Braided wire. Surrounded by earth berms.		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Braided wire.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ECD scrubber.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master & casing valves.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas engine.		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Controls crude oil tanks VOCs. Pilots: OFF   Shut-down.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	1	400 BBLs	STEEL AST		40.518980,-104.408727	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ produced H2O tank.						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment: Shares berms w/ crude oil tank.						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

**Inspected Facilities**

Facility ID: 285951 Type: WELL API Number: 123-24094 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI. Production valves shut. Flowline connected to Master valve (Tubing).  
COGCC records indicate last Prod: 02/2019.

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

**Comment:** Prior Insp:  
 Stormwater erosion around ECD on NE corner of location. Rutting along lease road to pump jack.  
 Refer to Rule 1002.f.  
 Install or repair required BMPs. Comply w/ Rule 1002.f.  
 Corrective Action date: 06/11/2018.

This insp:  
 \* Stormwater erosion around ECD on NE corner of location & rutting along lease road to pump jack NOW appears mitigated.  
 See photos #5-8.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 10/03/2019 at approximately 14:45 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: PDC ENERGY INC                      Location Name: BROWN-66N63W /2SEW                      Location ID: 306163                      Well Name: Brown 22-2                      API: 05-123-24094                      Location County: Weld County, Colorado                      Weather: Dry</p> <p>While there, I observed:                      Well(s): 1 ; Shut-In   SI. Production valves closed.                      Battery: Shut-down   Inactive</p> <p>Follow-up to Field Inspection Report Doc. #684905421 dated 05/11/2018.</p> <p>During this inspection the following prior possible compliance issues appear to be addressed:                      1.) Stormwater erosion around ECD on NE corner of location. Rutting along lease road to pump jack.                      Refer to Rule 1002.f.                      Install or repair required BMPs. Comply w/ Rule 1002.f.                      Corrective Action date: 06/11/2018.                      * Stormwater erosion around ECD on NE corner of location &amp; rutting along lease road to pump jack NOW appears mitigated.                      See photos #5-8.</p> <p>NO: New possible compliance issues observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/03/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101362	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4954823">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4954823</a>