

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2019

Submitted Date:

10/04/2019

Document Number:

690004419**FIELD INSPECTION FORM**Loc ID 436452 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436441	WELL	PR	01/01/2018	OW	123-39129	REYNOLDS CATTLE 6N-19HZ	PR
436451	WELL	SI	05/01/2019	OW	123-39138	REYNOLDS CATTLE 5C-23HZ	SI
436453	WELL	SI	06/01/2019	OW	123-39139	REYNOLDS CATTLE 6C-19HZ	SI
436454	WELL	PR	04/01/2019	OW	123-39140	REYNOLDS CATTLE 32N-23HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

					corrective date
Type: Plunger Lift	# 4				
Comment:					
Corrective Action:					Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery services at location number: 436962				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 436441 Type: WELL API Number: 123-39129 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 436451 Type: WELL API Number: 123-39138 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action:

Date: _____

Facility ID: 436453 Type: WELL API Number: 123-39139 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action:

Date: _____

Facility ID: 436454 Type: WELL API Number: 123-39140 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine inspection.	carlilec	10/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690004420	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4955475