

Interim Reclamation Inspection

May 30, 2019

Operator: NOBLE ENERGY INC - #100322

Location ID: 330389

Inspection Document #: 697500636

Weld County, CO

SWNW Section 36 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: EHRlich STATE PC F /36-32D

Location ID: 330389



Aerial imagery taken in 2017. Aerial imagery shows a flowline area in which the Operator disturbed within the last 1-2 years and has failed to properly reclaim per Reclamation rules.

Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



Photo 1. Photo taken from a portion of the flowline area on May 30, 2019, facing North. Photo illustrates a flowline area disturbance that has not been properly reclaimed per Reclamation rules. Photo illustrates bare ground with little, to no, establishment of reference area species.



Photo 2. Photo taken from a portion of the flowline area on May 30, 2019, facing East. See comments under Photo 1.

Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



Photo 3. Photo taken from a portion of the flowline area on May 30, 2019, facing South. See comments under Photo 1.



Photo 4. Reference photo taken southeast from the flowline area on May 30, 2019, facing South. See comments under Photo 1.

Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



Photo 5. Photo taken from a portion of the flowline area, facing North. Photo illustrates similar conditions from the prior inspection (i.e., flowline area disturbance that has not been properly reclaimed per Reclamation rules). Operator has failed to respond to the previous complaint filed in May 2018 by contacting the landowner to determine mitigating measures that will allow reclamation work to be conducted in such a manner as to not interfere with agricultural activities or crop production.



Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



Photo 6. Photo taken from a portion of the flowline area, facing East. See comments under Photo 5.

Inspection Photos

Location Name: EHRLICH STATE PC F /36-32D

Location ID: 330389



Photo 7. Photo taken from the nearby well (API#123-32549), facing South. Photo illustrates unused equipment that shall be removed per Rule 603.f.