

Inspection Photos
Location Name: Argenta CPD
Facility ID #467437



Heated AST does not have signage required by Rule 210.d.



Stained gravel below load out valve.

Inspection Photos
Location Name: Argenta CPD
Facility ID #467437



Filter dumpster inside secondary containment.



Stained soil and gravel near northern edge of location.

Inspection Photos
Location Name: Argenta CPD
Facility ID #467437



Stained soil and gravel at northern edge of compressor building.



Stained soil and concrete around southernmost compressor.

Inspection Photos
Location Name: Argenta CPD
Facility ID #467437



Unlabeled, unused chemical container.



Filter dumpster in secondary containment on upper level of facility.

Inspection Photos
Location Name: Argenta CPD
Facility ID #467437



Storm water erosion along SE edge of upper level of facility.



Unused equipment stored on upper level of facility.

Inspection Photos
Location Name: Argenta CPD
Facility ID #467437



Storm water erosion in SW corner of upper level of facility.



Erosional channel along southeastern edge of upper level.