

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/23/2019

Submitted Date:

10/05/2019

Document Number:

688305836**FIELD INSPECTION FORM**

Loc ID 317084 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 76830Name of Operator: SCHMID PROPERTIES INCAddress: PO BOX 389City: HICO State: TX Zip: 76457**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schmid, William	337-261-1500	tenniswilliam123@cs.com	
Walker, Carolyn	254-796-2100	schmidprop@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236016	WELL	SI	05/01/1995	OW	121-08506	CLARK 2-35	PA

General Comment:

PA Inspection

Cut, cap and cover on 10/2/2019, not witnessed (on vacation).

Inspected FacilitiesFacility ID: 236016 Type: WELL API Number: 121-08506 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: Bohler

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 4553, 4490, 211Cement Volume (sx): 104Good Return During Job: YESCement Type: Class GComment: 9/23/2019 wireline-Brand X. Got approval from DS so set plug at 4490' on 9/23/2019.Circulated at shoe plug prior to pumping cement.
Tagged shoe plug at 100' so topped off with 12 sxs cement.

Corrective Action: _____

Date: _____

WorkoverComment: Bohler Rig #5, Ryan

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305930	Schmid Properties Clark 2-35 PA Form 17	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956057
688305931	Schmid Properties Clark 2-25 Rig 9/23/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956058
688305932	Schmid Properties Clark 2-25 Rig 9/24/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956059
688305933	Schmid Properties Clark 2-25 well sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956060