

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/23/2019

Submitted Date:

10/05/2019

Document Number:

688305870**FIELD INSPECTION FORM**
 Loc ID 317004 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 35190Name of Operator: GRAYHORSE OPERATING INCAddress: 20 EAST 5TH ST STE 320City: TULSA State: OK Zip: 74103**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ellis, Charles	(918) 382-9201	caellis@grayhorse.net	
Crumley, Tim	(970) 768-5658	tcrumley@tcrumleypumpingse vice.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234358	WELL	PR	05/10/1965	OW	121-06469	V.A. QUERY 1	PR

**General Comment:**

Reinspection, Corrective Actions Completed, Form 19I, Form 19S (resolved) #402151841 and analytical data were submitted to cover both the 7/15/2-10 and 6/25/2019 inspections. COGCC EPS contacted and the flowline trench can be closed.

**Inspected Facilities**Facility ID: 234358 Type: WELL API Number: 121-06469 Status: PR Insp. Status: PR**Producing Well**Comment: PR. Pumper said that the well is turned back on.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305925	Grayhorse Operating V.A. Query 1 well sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956080">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956080</a>
688305926	Grayhorse Operating V.A. Query 1 flowline trench	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956081">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956081</a>