

Inspection Photos

API#045-06481

Operator: Maralex

Inspection: #692401406

Inspection Date: 9/27/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast. Note debris weeds around equipment.

September 27, 2019



Photo#2:

View over Blowdown Pit. Maintenance of netting and weeds has not been performed.

September 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06481



Photo#3:

Stormwater is undercutting Rip Rap at NW side of access road culvert & eroding ditch. Erosion is also occurring on access road.

September 27, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Maralex Albertson API#045-06481