

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/22/2019

Submitted Date:

10/06/2019

Document Number:

688305935**FIELD INSPECTION FORM**
 Loc ID 317086 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 76830Name of Operator: SCHMID PROPERTIES INCAddress: PO BOX 389City: HICO State: TX Zip: 76457**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schmid, William	337-261-1500	tenniswilliam123@cs.com	
Sutphin, Dirk		dirk.sutphin@state.co.us	COGCC Engineer
Walker, Carolyn	254-796-2100	schmidprop@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236022	WELL	PR	11/06/1992	OW	121-08512	CLARK 10-35	PR

General Comment:[Reinspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 377-261-1500 and 970-554-1988 (check that all emergency contact numbers are current)

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at wellhead and under pump jack (see attached photos). Manifest waste for disposal.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/03/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	wire panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	gas, propane		
Corrective Action:		Date:	
Type: Pump Jack	#		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

			CENTRALIZED BATTERY		,		
Comment:							
Corrective Action:						Date:	
Paint							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No							
Comment:							
Corrective Action:					Date:		
Flaring:							
Type							
Comment:							
Corrective Action:					Date:		

Inspected Facilities

Facility ID: 236022 Type: WELL API Number: 121-08512 Status: PR Insp. Status: PR

Producing Well

Comment: PR. Jun 2019 production reported to COGCC database. There is a gap in reported production between Jun 2008 and Mar 2012-contact COGCC Engineering.

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

Pumper was contacted on 9/24/2019 about engine stained soil and said that location was cleaned up at the time of the cut, cap and cover of the Clark 2-35 PA on or around 10/1/2019. Inspector will reinspect for stained soil.

ShermaSe

10/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688305958	Schmid Properties Clark 10-35	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956151