

Inspection Photos
Operator: BP America
Location/API #: 067-08630
Date: 9-30-2019



Photo 1 View of the project area from the well pad entrance facing center.



Photo 2. View of the fill slope in the eastern project area from the southeastern corner facing northward. Revegetation is comprised of grasses such as western wheatgrass, sand dropseed, and slender wheatgrass.



Photo 3. View of cattle guard within the southeastern portion of the interim reclamation area, needs to be removed.



Photo 4. View of headcut within the eastern project area. Erosion appears to be continuing here as cobble is not sufficient to stabilize erosion.



Photo 5. View from headcut (next to hardhat) facing downslope. Erosional channel is approx. 2 feet wide and deep.



Photo 6. View of reference area vegetation, comprised of ponderosa pine forest with gambel oak and herbaceous understory.