

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2019

Submitted Date:

10/07/2019

Document Number:

690900077

FIELD INSPECTION FORM

Loc ID 324754 Inspector Name: FISCHER, ALEX On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Laird, Spence		slaird@sandridgeenergy.com	
Waldron, Emily		emily.waldron@state.co.us	
Church, Matt		mchurch@sandridgeenergy.com	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296567	WELL	PR	02/13/2015	OW	057-06469	SPICER 3-32H	EI

General Comment:

On October 4, 2019, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Spicer 3-32H Location (Location ID: 324754) API 057-06469 and REM 13906. Weather was sunny and temperatures about 59 degrees Fahrenheit.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: [Stainless steel line \(trash/debris\).](#)

Corrective Action: [Comply with Rule 603.f .](#)

Date: 10/17/2019

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 296567 Type: WELL API Number: 057-06469 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: Approximate 3-inch oil stain noted on ground surface beneath a 4-inch hammer union located between the two southern tanks. Apparent oil stain (12-18-inches) on the ground surface near the northwest corner of the tank battery.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Date: 11/07/2019

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
Comment					
Corrective Action					Date: _____
Drums, Buckets, Containers	Other	Inadequate			
Comment	A 5-gallon pail with oily rag near the southern end of the Location where equipment and a soil stock pile were noted.				
Corrective Action	Comply with Rule 603.f .				Date: <u>10/17/2019</u>

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Provide update to REM 13906.	fischera	10/07/2019
Provide SandRidge staff and contractor training to inspect and tighten all hammer unions on a routine basis.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690900078	IINSP Photo Spicer 3-32H Location 324754 20191004	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956953