

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/07/2019

Submitted Date:

10/07/2019

Document Number:

696101372

FIELD INSPECTION FORM

Loc ID 428456 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 16 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428457	WELL	PR	04/01/2019	OW	123-35367	North Platte 14-36	SI
428616	WELL	PR	05/01/2019	OW	123-35441	Latham F-J-1HZ	SI
428618	WELL	PR	10/01/2018	OW	123-35443	North Platte X-D-35HZ	PR

General Comment:

This is a WELL & BATTERY inspection.
Well(s): 3
(1: Producing | PR ; 2: Shut-In | SI).
Battery: Active.

Follow-up to Field Inspection Doc. #696101310 dated 09/17/2019.

Location

Lease Road:			
	Type	Access	
	comment:	Adequate	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	BATTERY	
	Comment:		
Corrective Action:			Date:
	Type	TANK LABELS/PLACARDS	
	Comment:		
Corrective Action:			Date:
	Type	CONTAINERS	
	Comment:		
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	OTHER		
	Comment:	<p>Prior insp: Oily waste. Stained soil appears at crude oil tank loadline area. Stained soil appears between 2nd - 4th tanks from east going west. Refer to Rule 907.e. Remove or remediate stained soil at crude oil tank loadline area. Comply w/ Rule 907.e. Corrective Action date: 10/17/2019.</p> <p>This insp: * Oily waste. Stained soil NOW appears mitigated at crude oil tank loadline area. Stained soil NOW appears mitigated between 2nd - 4th tanks from east going west. See photos #6-9.</p>	
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	3: Wellheads ; Iron panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 15		
Comment:	4: ECD scrubbers 5: Chemical pumps, plastic drums, drip containment 2: Metal tanks, drip containment (Methanol) 4: Metal tanks, drip containment (Coolant)		
Corrective Action:		Date:	
Type: VRU	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	Controls crude oil tanks VOCs. Pilots: ON		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	CONCRETE SUMP/VAULT		,

Comment:						Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)	60 Bbls.						
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ crude oil tanks & produced H2O tanks.				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	300 BBLS	STEEL AST				
Comment:						Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ crude oil tanks & produced H2O vaults.				Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	10	400 BBLS	STEEL AST		40.352353,-104.389715		
Comment:		Equalizer lines connect 8 of 10 crude oil tanks.				Date:	
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:		Shares berms w/ produced H2O tanks / vaults.				Date:	
Corrective Action:						Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 428457 Type: WELL API Number: 123-35367 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In. | SI.
Observed production valves closed at well.

Corrective Action: _____ Date: _____

Facility ID: 428616 Type: WELL API Number: 123-35441 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In. | SI.
Observed production valves closed at well.

Corrective Action: _____ Date: _____

Facility ID: 428618 Type: WELL API Number: 123-35443 Status: PR Insp. Status: PR

Producing Well

Comment: Producing | PR.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 10/07/2019 at approximately 11:55 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /14-36 Location ID: 428456 Location County: Weld County, Colorado Weather: Dry</p> <p>While there, I observed: Well(s): 3 ; (1: Producing PR ; 2: Shut-In SI).</p> <p>Follow-up to Field Inspection Doc. #696101310 dated 09/17/2019.</p> <p>During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Oily waste. Stained soil appears at crude oil tank loadline area. Stained soil appears between 2nd - 4th tanks from east going west. Refer to Rule 907.e. Remove or remediate stained soil at crude oil tank loadline area. Comply w/ Rule 907.e. Corrective Action date: 10/17/2019. * Oily waste. Stained soil NOW appears mitigated at crude oil tank loadline area. Stained soil NOW appears mitigated between 2nd - 4th tanks from east going west. See photos #6-9.</p> <p>NO: New possible compliance issues observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/07/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101373	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956954