

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type PUMP JACK

Comment: 4' Barb wire

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment # 2

Comment: electric boxes

Corrective Action:

Date:

Type: Pump Jack # 1

Comment:

Corrective Action:

Date:

Type: Prime Mover # 1

Comment: electric motor

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 240904 Type: WELL API Number: 123-08692 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	10/07/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500160	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957044