

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/07/2019

Submitted Date:

10/07/2019

Document Number:

699100280**FIELD INSPECTION FORM**

Loc ID 323668 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                                  | Comment                         |
|--------------|-------|--|---------------------------------|
| Kraich, Adam |       | adam.kraich@state.co.us                |                                 |
| ,            |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 245549      | WELL | SI     | 09/01/2017  | OW         | 123-13344 | KISSLER 3-2   | TA          |

**General Comment:**

**Location**Overall Good: ☒

|                      |          |       |  |
|----------------------|----------|-------|--|
| <b>Signs/Marker:</b> |          |       |  |
| Type                 | WELLHEAD |       |  |
| Comment:             | Adequate |       |  |
| Corrective Action:   |          | Date: |  |

|                           |          |       |  |
|---------------------------|----------|-------|--|
| Emergency Contact Number: |          |       |  |
| Comment:                  | Adequate |       |  |
| Corrective Action:        |          | Date: |  |

|                           |   |       |            |
|---------------------------|---|-------|------------|
| <b>Good Housekeeping:</b> |   |       |            |
| Type                      | WEEDS   |       |            |
| Comment:                  | Weeds grown around wellhead need to be removed for good house keeping. See photos attached. |       |            |
| Corrective Action:        | Comply with Rule 603.f .  | Date: | 10/16/2019 |

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           | Panel    |       |  |
| Corrective Action: |          | Date: |  |

|                    |                                   |       |                 |
|--------------------|-----------------------------------|-------|-----------------|
| <b>Equipment:</b>  |                                   |       | corrective date |
| Type: Plunger Lift | # 1                               |       |                 |
| Comment:           |                                   |       |                 |
| Corrective Action: |                                   | Date: |                 |
| Type: Bradenhead   | # 1                               |       |                 |
| Comment:           | Appears to be plumbed to surface. |       |                 |
| Corrective Action: |                                   | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**Facility ID: 245549 Type: WELL API Number: 123-13344 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: T/A , Has yellow "LTSI" variance tag, and orange decommissioned facility variance tag.  
Well is not connected to a flowline.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Monday October 7, 2019 at approximately 0730 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Kissler 3-2 of Noble Energy, at Location # 323668 Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds grown around wellhead need to be removed for good housekeeping. Comply with Rule 603.f .</p> <p>With a corrective date of 10/16/19.</p> <p>See attached photos</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p> | burnsa | 10/07/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 699100281    | photos      | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957111">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957111</a> |