

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------|-------|--|
| Comment: | Adequate | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|----------------------------------|-------|------------|
| Type | WEEDS | | |
| Comment: | Weeds grown around the wellhead. | | |
| Corrective Action: | Comply with Rule 603.f . | Date: | 11/04/2019 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | Date: | |
| Type | SEPARATOR | | |
| Comment: | Wire | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Wire | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|---|---|----------|--------------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV CONCRETE | | , |
| Comment: Shares containment with crude oil tank | | | | | |

| | |
|--------------------|-------|
| Corrective Action: | Date: |
|--------------------|-------|

Paint

| | | | |
|------------------|---------|--|--|
| Condition | | | |
| Other (Content) | | | |
| Other (Capacity) | 48 BBLS | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|-----------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 40.341480,-104.519350 |

| | | |
|--------------------|--|-------|
| Comment: | | |
| Corrective Action: | | Date: |

Paint

| | | | |
|------------------|----------|--|--|
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) | | | |
| Other (Type) | | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|----------------------------------|
| Earth | Adequate | Walls Insufficient | Base Sufficient | Inadequate |
| Comment: Berm wall for Tank Battery needs to be repaired. | | | | |
| Corrective Action: Repair berms per Rule 906.d.(1). | | | | Date: 11/04/2019 |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected FacilitiesFacility ID: 245032 Type: WELL API Number: 123-12827 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Monday October 7, 2019 at approximately 0800 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at FHA 2-1 of Noble Energy, at Location # 323294 Weld County, Colorado. During this inspection the following possible compliance issues were observed: Weeds grown around wellhead need to be removed for good housekeeping. Comply with Rule 603.f . With a corrective date of 11/4/19. Berm wall for Tank Battery needs to be repaired. Repair berms per Rule 906.d.(1). With a corrective date of 11/4/19 See attached photos A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing education inspections</p> | burnsa | 10/07/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 699100283 | photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957112 |