

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402202287

Date Received:

10/08/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

robfoos@tcenergyllc.com

ediefitzgerald@tcenergyllc.com

ronaldmack@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901231

Inspection Date: 09/12/2019

FIR Submit Date: 09/13/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308966

Location Name: APACHE CANYON-634S67W Number: 18SWNE County: LAS ANIMAS

Qtrqr: SWNE Sec: 18 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.087418 Longitude: -104.926258

FACILITY - API Number: 05-071- -00 Facility ID: 285970

Facility Name: APACHE CANYON Number: 18-07

Qtrqr: SWNE Sec: 18 Twp: 34S Range: 67W Meridian: 6

Latitude: 37.087418 Longitude: -104.926258

CORRECTIVE ACTIONS:

1 CA# 130556

Corrective Action: Comply with Rule 603.f.
Remove unused equipment.

Date: 10/14/2019

Response: CA COMPLETED

Date of Completion: 10/03/2019

The sound walls were in the way of BMP implementation activities. The BMP's were installed and the sound wall

Operator Comment: were put back in place. See attached photo log for details.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 130557

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/14/2019

Response: CA COMPLETED

Date of Completion: 10/03/2019

Operator Comment: The bar ditch was dominated to direct run off to the culvert inlets. Erosion control blankets were installed to stabilize the disturbed soil. Rock socks were installed in the bar ditch to filter sediment. See photo attachment for details.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR. Environmental Tech.

Date: 10/8/2019 7:59:04 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402202291	Photo Log
-----------	-----------

Total Attach: 1 Files