

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/08/2019

Submitted Date:

10/08/2019

Document Number:

699300337

**FIELD INSPECTION FORM**

Loc ID 317651 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Findings:**

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Pesika, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239692	WELL	PR	03/20/1995	GW	123-07480	SUCKLA-BROWN UNIT 1	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

	Type PUMP JACK		
	Comment: Hog fence		
Corrective Action:		Date:	

**Equipment:**

Type	Description	#					corrective date
Ancillary equipment		# 1					
	Comment: Electric panel, transformers and meter box						
Corrective Action:							Date:
Prime Mover		# 1					
	Comment: electric motor						
Corrective Action:							Date:
Pump Jack		# 1					
	Comment:						
Corrective Action:							Date:
Bradenhead		# 1					
	Comment: appears to be plumbed to surface						
Corrective Action:							Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 239692 Type: WELL API Number: 123-07480 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Tuesday 10/8/19 at approximately 0900 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at the Suckla-Brown KP Kauffman, at API #05-123-07480 in Weld County Colorado, this is a follow up inspection per Doc. # 699300013.                      While there, I observed a producing wellsite.                      During this inspection the following compliance issues appear to have been addressed:                      210.e : Wellhead sign appears to have been updated see photo #1.                      605.d : 1" valve on tubing line leaking appears to have been tightened/replaced see photo #3.                      907.e : Stained soil from leaking valve appears to have been addressed see photo #3.                      Location is dry, weather is cloudy.                      No follow up on this site inspection needs to be conducted.                      Compliance issues appear to have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	10/08/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300338	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957718">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957718</a>