

Inspection Photos
Location Name: Federal RU 31-17
Location ID: 452011
Inspection Date: September 23, 2019



Photo #1 – Aerial view of the location.



Photo #2 – View of the risers around the well conductors.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Federal RU 31-17
Location ID: 452011
Inspection Date: September 23, 2019



Photo #3 – View of the risers located northwest of the well conductors on the northwest corner of the well pad.



Photo #4 – View of uncapped, unmarked flowlines.

Inspection Photos
Location Name: Federal RU 31-17
Location ID: 452011
Inspection Date: September 23, 2019



Photo #5 – View of the flowline located northwest of the tank battery.



Photo #6 – View of the unused flowline manifold.

Inspection Photos
Location Name: Federal RU 31-17
Location ID: 452011
Inspection Date: September 23, 2019



Photo #7 – View of the unlabeled tank and battery.



Photo # - View of the unused trough and risers located on the northwest corner of the well pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Federal RU 31-17
Location ID: 452011
Inspection Date: September 23, 2019



Photo #9 – View of the cuttings trench looking southeast.



Photo #10 – View of the cuttings trench looking northwest.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Federal RU 31-17
Location ID: 452011
Inspection Date: September 23, 2019



Photo #11 – View of the surface casing cuttings on the southeast side of the cuttings trench.



Photo #12 – View of the surface casing cuttings and the cuttings trench looking northwest.

