

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/08/2019

Submitted Date:

10/08/2019

Document Number:

679601716**FIELD INSPECTION FORM**
 Loc ID 323190 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244891	WELL	SI	04/01/2017	GW	123-12686	FLATIRON 10-36	SI
447225	TANK BATTERY	AC	08/05/2016		-	FLATIRON-66N66W 36NWSE	AC

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	SI/TA well per variance doc#401474555. Orange tag for SI/TA status not present.		
Corrective Action:	Install tags to comply with doc#401474555	Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in gas meter house, inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/23/2019
Type	DEBRIS		
Comment:	Weeds/debris inside wellhead fencing. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/18/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	48 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tank .			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.442500,-104.721000
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 244891 Type: WELL API Number: 123-12686 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA; MIT requirement waived per variance doc#401474555.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 447225 Type: TANK API Number: - Status: AC Insp. Status: AC

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 696300121. ORANGE DECOMMISSION TAG STILL NOT INSTALLED ON WELLHEAD. 2 NEW CORRECTIVE ACTIONS ARE ASSIGNED TO THIS LOCATION.</p> <p>On Tuesday, October 8, 2019 at approximately 15:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at FLATIRON 10-36 (Noble Energy), at location #: 323190 in WELD COUNTY Colorado.</p> <p>While there, I observed a temporarily abandoned wellhead and shut in facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. Unused equipment inside gas meter house and inside wellhead fencing. COMPLY WITH RULE 603.F. (Corrective Action Date: October 23, 2019) See attached photo #2,5.</li> <li>2. Debris/weeds inside wellhead fencing. COMPLY WITH RULE 603.F. (Corrective Action Date: October 18, 2019) See attached photo #2.</li> </ol> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	10/08/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679601717	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4958591">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4958591</a>