

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2019

Submitted Date:

10/02/2019

Document Number:

679601696**FIELD INSPECTION FORM**
 Loc ID 333026 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10110Name of Operator: GREAT WESTERN OPERATING COMPANY LLCAddress: 1001 17TH STREET #2000City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@gwogco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286095	WELL	SI	01/01/2019	GW	123-24123	GREAT WESTERN 27-54	TA
286701	WELL	TA	01/31/2018	GW	123-27277	GREAT WESTERN 27-43	TA
286702	WELL	SI	01/01/2019	GW	123-27276	GREAT WESTERN 27-44	SI
287296	WELL	TA	01/31/2018	GW	123-24286	GREAT WESTERN 27-33	TA
287297	WELL	SI	01/01/2019	GW	123-24285	GREAT WESTERN 27-34	SI

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate (x5)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No NFPA placard on H2O tank. See attached photo.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Nest on wellhead. See attached photo.		
Corrective Action:	Comply with Rule 603.f.	Date:	10/12/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	6' chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' chain link (x5)		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6' chain link		
Corrective Action:		Date:	

**Equipment:**

Type: Bird Protectors	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 5		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	150 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares containment with other tanks.				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--

**Inspected Facilities**

Facility ID: 286095 Type: WELL API Number: 123-24123 Status: SI Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA

Corrective Action:  Date:

Facility ID: 286701 Type: WELL API Number: 123-27277 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA

Corrective Action:  Date:

Facility ID: 286702 Type: WELL API Number: 123-27276 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

Facility ID: 287296 Type: WELL API Number: 123-24286 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: TA

Corrective Action:  Date:

Facility ID: 287297 Type: WELL API Number: 123-24285 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI

Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 696300110. ALL CORRECTIVE ACTIONS ASSIGNED IN PREVIOUS INSPECTION DOC#: 696300110 HAVE BEEN COMPLETED. TWO NEW CORRECTIVE ACTIONS HAVE BEEN ASSIGNED TO THIS LOCATION. SEE ATTACHED PHOTOS.</p> <p>On Wednesday, October 2, 2019 at approximately 14:01, I, Inspector Brittani Santistevan, conducted an on-site inspection at GREAT WESTERN PAD6 (Great Western Oil &amp; Gas), at location #: 333026 in WELD COUNTY Colorado.</p> <p>While there, I observed temporarily abandoned wellheads/shut in wellheads/facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. Appears to be a birds nest on wellhead (Great Western 27-43) COMPLY WITH RULE 603.F. (Corrective Action Date: October 12, 2019) See attached photo #5.</li> <li>2. No NFPA placard on Produced water tank. INSTALL SIGN TO COMPLY WITH RULE 210.D. (Corrective Action Date: November 2, 2019) See attached photo #14.</li> </ol> <p>BBLs are fading on all tanks, recommend relabeling tanks before they become not legible. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Education Inspection.</p>	santistb	10/02/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402197073	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4953430">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4953430</a>
679601697	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4953417">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4953417</a>