

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/08/2019

Submitted Date:

10/09/2019

Document Number:

699400068**FIELD INSPECTION FORM**
 Loc ID 322274 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 17210Name of Operator: CINNAMON CREEK OIL & GAS INCAddress: P O BOX 544City: WALSH State: CO Zip: 81090**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections
,	,	dnr_cogccenforcement@state.co.us	COGCC Enforcement

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210097	WELL	PR	04/01/2019	OW	043-40034	LOBACH 1	EI

General Comment:

This is a follow up inspection to COGCC Inspection #682600588 which found a 1" ball valve venting gas at the time of inspection on 12/20/2018 (NOAV 401954589 issued). Current inspection found the valve and piping to the valve have been removed (see attached photo).

A 4 gas meter detected 29 lower explosive limit (LEL) at the base of the wellhead (see attached video). LEL of 18 was detected approximately 10 feet from wellhead. Well is located in an suburban area in between two single family homes. Operator informed of leak via phone call on 10/8/2019 and field personnel were on site to address mechanical issue the afternoon of 10/8/19.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	4 gas meter detected 29 lower explosive limit (LEL) at the base of the wellhead (see attached video). LEL of 18 was detected approximately 10 feet from wellhead. At the time of issuance of this inspection operator has had field personnel fix leak issue (phone call 0915 10/9/2019).		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	10/10/2019

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210097 Type: WELL API Number: 043-40034 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699400070	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4958836
699400071	Inspection video	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4958837