

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/09/2019

Submitted Date:

10/03/2019

Document Number:

688800631**FIELD INSPECTION FORM**Loc ID 325974 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	
Walker, Mandi	505-324-5122	mwalker@hilcorp.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215662	WELL	PR	01/23/1996	GW	067-07267	BONDAD 33-10 100	EI
466710	SPILL OR RELEASE	CL	08/15/2019		-	SPILL/RELEASE POINT	EI

General Comment:

On September 9, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Hilcorp Bondad 33-10 #100. For the most recent field inspection report of this facility, please refer to document #688800604. COGCC West Environmental Supervisor Alex Fischer was present during this field inspection.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Free standing sign near PBV.			
Corrective Action:				Date:
Type	BATTERY			
Comment:	ASTs do not have NFPA placards.			
Corrective Action:	Install sign to comply with Rule 210.d. FIRR #402183993 received on 9/20/19 reported that this corrective action from the previous inspection report has been completed			Date: 10/21/2019
Type	TANK LABELS/PLACARDS			
Comment:	PBV has sign labeled with contents, capacity, and NFPA placard.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Posted on location signs.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Fencing, pipe, and other unused equipment stored in NW corner of location has been removed.			
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Perimeter fencing around PBV secondary containment berm.			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Guard fencing present.			
Corrective Action:				Date:
Equipment:				
Type: Ancillary equipment	# 1			corrective date
Comment:	Compressor/storage building			

Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	Skid mounted.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Pump house.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<50 BBLS	PBV STEEL		37.129477,-107.935173	
Comment:	Open topped steel PBV with expanded metal cover.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	45 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLS	HEATED STEEL AST		37.129153,-107.936011
Comment:					

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>215662</u>	Type:	<u>WELL</u>	API Number:	<u>067-07267</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>466710</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>CL</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil containers.
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On September 9, 2019 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Hilcorp Bondad 33-10 #100. For the most recent field inspection report of this facility, please refer to document #688800604. COGCC West Environmental Supervisor Alex Fischer was present during this field inspection.</p> <p>During this inspection it was noted that:</p> <p>The areas of stained soil observed during the previous inspection have been cleaned up.</p> <p>The unused equipment in the NW corner of the location has been removed.</p> <p>The tank battery is not posted with an NFPA placard.</p> <p>FIRR Document #402183993 received on 9/20/19 indicated that the ASTs are now posted with NFPA placards.</p>	hughesjo	10/03/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402198844	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4954464
688800632	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4954450