

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Location 463141



Off loading operations, left side of picture.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Off loading operations in process.



Vaneta SWD Facility Location ID 324752.



Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Trash just off of the Location.



Stained soil/gravel in multiple areas of Location and vehicle tracking.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Stained soil/gravel in multiple areas of Location and vehicle tracking.



Oily water/fluids pooled on liner in secondary containment.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Oily water/fluids pooled on liner in secondary containment.



Delivery hose directly on liner of secondary containment.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Delivery hose directly on liner of secondary containment and residual oil and salt staining.



Delivery hose directly on liner of secondary containment.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Black bag on pallet and oily soaked catch mat.



Oily water/fluids pooled on liner in secondary containment, 1" by app 30' pipe directly on liner of secondary containment.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Oily water/fluids pooled on liner in secondary containment, 1" by app 30' pipe directly on liner of secondary containment.



Trash/debris in off load area, impacted by oily waste and is now considered E&P waste.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Trash/debris in off load area, impacted by oily waste and is now considered E&P waste.



Drips and staining of oil on the recently placed gravel at the load out area.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Drips and staining of oil on the recently placed gravel at the load out area.



Drips and staining of oil on the recently placed gravel at the load out area and oily soaked catch mats.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Oily water/fluids pooled on liner in secondary containment.



Unused equipment on east berm.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Oily water/fluids pooled on liner in secondary containment and sorbent material.



Oily water/fluids pooled on liner in secondary containment and sorbent material.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Oily water/fluids pooled on liner in secondary containment and sorbent material.



Oily water/fluids pooled on liner in secondary containment and sorbent material. Improper storage of ladder.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



**Oily water/fluids pooled on liner in secondary containment.
Uncapped valve with bull plug on liner.**



**Oily water/fluids pooled on liner in secondary containment, 1" by
app 30' pipe directly on liner of secondary containment.**

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Note pipe supports at an angle which may potentially compromise the liner. Also, debris (wood and metal pipe).



Oily stained soil outside of secondary containment on north side of tank battery.

Inspection Photos
Location Name: Vaneta DAF
Location 324752, CE&P Facility 463141



Off loading in 400 bbl tank near DAF. Note: Spill containment bucket under truck valve, but no impervious containment to the ground surface.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources