

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/09/2019

Submitted Date:

10/04/2019

Document Number:

688800635

FIELD INSPECTION FORM

Loc ID 467436 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 16 Number of Comments
- 8 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Shorty, Priscilla		pshorty@hilcorp.com	
Ray, Mandi	505-324-5122	mray@hilcorp.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Lutz, Deborah		debbie.lutz@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467437	GAS COMPRESSOR STATION	AC	09/12/2019		-	Argenta CPD	EI

General Comment:

On September 9, 2019 COGCC West Environmental Supervisor Alex Fischer and SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Argenta CPD. Hilcorp representative Chad Murphy was on site during this inspection. Location ID #467436 has been created in the COGIS database for the Argenta CPD. Facility ID #467437 has also been created in the COGIS database for this facility.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Cube shaped vessel and adjacent open topped below grade vessel are not labeled per Rule 210.d.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 11/04/2019
Type	TANK LABELS/PLACARDS		
Comment:	"Slop tank #1" does not have signage required by Rule 210.d. Conoco Phillips sticker labeling AST as a produced water tank is from previous operator.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 11/04/2019
Type	OTHER		
Comment:	Free standing location sign near entrance to location.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Approximately 95 bbl. fiberglass open topped vessel is not labeled with capacity.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information was not observed on any location signs.		
Corrective Action:	Install sign to comply with Rule 210.d.		Date: 11/04/2019
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on upper level of facility.		
Corrective Action:	Comply with Rule 603.f.		Date: 01/04/2020
Type	STORAGE OF SUPL		
Comment:	Unused equipment stored on upper level of facility.		
Corrective Action:	Comply with Rule 603.f.		Date: 01/04/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil			
Comment:	Several areas of stained soil and gravel observed during this inspection. Most notable are areas north of compressor building, surrounding the southernmost compressor, and near the northern entrance to the compressor building.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 11/04/2019
Produced Water	Truck Loadout	<= 1 bbl	
Comment:	Stained soil beneath truck load out valve on AST.		

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.	Date: <u>11/04/2019</u>
---	-------------------------

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Chain link perimeter fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		37.129232,-107.936964
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	Open topped vessel is not labeled with capacity.
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		37.130118,-107.937737
Comment:					

Corrective Action:	Date:
--------------------	-------

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Unknown	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		37.129177,-107.937133
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Open topped tank is not labeled with capacity.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	HEATED STEEL AST		37.129219,-107.937236
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Capacity unknown	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 467437 Type: GAS API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	Drip pots on load out valves.
Compaction	In Process	Gravel	Pass	Material Handling And Spill Prevention	Pass	Drip pans beneath pumps.
Rip Rap	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil containers in secondary containment.

Comment: Erosional channels forming along southern edge of upper level. Sediment transport evident along northwestern edge of lower level. Stained soil and gravel in this immediate area suggest contaminant transport off site may be occurring.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/04/2019

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On September 9, 2019 COGCC West Environmental Supervisor Alex Fischer and SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Argenta CPD. Hilcorp representative Chad Murphy was on site during this inspection. Location ID #467436 has been created in the COGIS database for the Argenta CPD. Facility ID #467437 has also been created in the COGIS database for this facility.</p> <p>Erosional channels forming along southern edge of upper level. Sediment transport evident along northwestern edge of lower level. Stained soil and gravel in this immediate area suggest contaminant transport off site may be occurring.</p> <p>During this inspection, several areas of stained soil were observed. Most notable were areas to the northeast of the compressor building and below the load out valve on the "slop tank".</p> <p>Unused equipment is being stored on both levels of this facility.</p> <p>Ensure that all tanks are labeled with required information listed in Rule 210.d.</p> <p>The operator shall contact the COGCC Western Location Specialist within 60 days of this inspection being submitted regarding Form 2A applicability for this facility.</p> <p>The operator shall contact the COGCC Financial Assurance Analyst within 60 days of submission of this inspection regarding this facility.</p>	hughesjo	10/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402200626	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4955891
688800636	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4955889