

Location			
Lease Road:			
Type	Access		
comment:	Weeds growing on Access road to wellhead		
Corrective Action:	Comply with Rule 603.f .	Date:	10/18/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds actively growing on entire location, see photos		
Corrective Action:	Comply with Rule 603.f .	Date:	10/18/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be surface		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.472150,-104.165780
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 272250 Type: WELL API Number: 123-22214 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 10/04/2019 approximately 10:45, I, Inspector Erica Petrie, conducted a Field Inspection at Smith Energy Corp, Schettler 12-24 at Location #332375 in Weld County, Colorado. While there, I observed Production Operations During this inspection the following possible compliance issues were observed: Weeds at Wellhead, Tank Battery, Separator, see photos. Remove, manage, & control weeds at wellsite and tank battery. Refer to Rule 603.f (10 Days). Comply with Rule 603.f. Corrective Action date of 10.18.2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspection.</p>	petrie	10/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402200474	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4955769
696300642	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4955762