

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2019

Submitted Date:

10/04/2019

Document Number:

696300643**FIELD INSPECTION FORM**

Loc ID 327562 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Smith, Glenn	(970) 381-6253	gsmithten@what-wire.com	
Kraich, Adam		adam.kraich@state.co.us	
Smith, Chris	(303) 709-6157	smithenergy@live.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247064	WELL	SI	06/01/2018	OW	123-14861	TAYLOR 15-1	SI

General Comment:

Location			
Lease Road:			
Type	Main		
comment:	Weeds actively growing on main road to Tank Battery, see photos		
Corrective Action	Comply with Rule 603.f .	Date:	10/18/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds at Tank battery		
Corrective Action:	Comply with Rule 603.f .	Date:	10/18/2019
Type	WEEDS		
Comment:	Weeds at Pumping Unit		
Corrective Action:	Comply with Rule 603.f .	Date:	10/18/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		

Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		40.482310,-104.185610	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:	Date:		

Flaring:

Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	247064	Type:	WELL	API Number:	123-14861	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Weeds actively growing in Pit

Corrective Action

Comply with Rule 603.f .Date: 10/18/2019**Fencing:**Fencing Type: Fencing Condition: Comment:

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment:

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment:

Corrective Action

Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 10/04/2019 approximately 10:23, I, Inspector Erica Petrie, conducted a Field Inspection at Smith Energy Corp, Taylor 15-1 at Location #332375 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds at Pumping Unit, Tank Battery, Pit and Heater Treater, see photos. Remove, manage, & control weeds at wellsite, tank battery, treater, & H2O pit. Refer to Rule 603.f (10 Days). Comply with Rule 603.f. Corrective Action date of 10.18.2019</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing Educational Inspection.</p>	petrie	10/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402200475	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4955770
696300644	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4955763