

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/08/2019

Submitted Date:

10/11/2019

Document Number:

689901380

**FIELD INSPECTION FORM**

Loc ID 321012 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
LEVENGOD JOHN		jlevengood07@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205774	WELL	PR	04/01/2019	GW	009-06189	HEFLEY 2	RI

**General Comment:**

This is a follow up of the previous inspection document number 689901142.  
 The corrective actions of the previous inspection have not been performed.  
 Previous corrective action date remains for potential enforcement.  
 Corrective actions must be performed immediately.

**Location**Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No sign at meter shed/tank battery. Corrective action was not performed since previous inspection.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/14/2019
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/14/2019

**Emergency Contact Number:**

Comment:	No emergency contact number.		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	There is vegetation debris around the well which is a potential fire hazard.		
Corrective Action:	Comply with Rule 603.f . Remove debris near the well equipment.	Date:	10/18/2019
Type	UNUSED EQUIPMENT		
Comment:	There is unused equipment and debris at the tank battery and meter shed location. Corrective action was not performed since previous inspection.		
Corrective Action:	Comply with Rule 603.f . Removed unused equipment and debris.	Date:	09/14/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	Meter run is 575' East of wellhead. The meter shed is leaning and unstable and there is debris inside. This is a safety concern. Corrective action was not performed since previous inspection.		
Corrective Action:	Properly stabilize and secure meter shed. Keep door closed and remove debris. This is a safety issue and a good housekeeping requirement. Comply with Rule 603.f .	Date:	09/14/2019
Type: Gas Meter Run	# 1		
Comment:	There was no hissing sound or strong odor near the meter shed. Sign posted says well is shut in.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs			37.307830,-102.187200

Comment:	There is no secondary containment around the tank. Corrective action was not performed since previous inspection.				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).				Date: 09/15/2019

**Paint**

Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			
			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			
			Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion issues at the meter shed/tank battery site. The location is not stabilized.

Corrective Action: Install or repair required BMPs per Rule 1002.f.  
Corrective action was not performed since previous inspection.

Date: 09/14/2019

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689901381	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961392">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961392</a>