

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2019

Submitted Date:

10/09/2019

Document Number:

687905639**FIELD INSPECTION FORM**

Loc ID 312036 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**21 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270	WELL	PR	02/04/2008	GW	067-09492	BELLINO 3	PR
215369	WELL	PR	07/07/1989	GW	067-06974	BELLINO 1	PR

General Comment:

[Site inspection and equipment inventory with photos at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Labels/placards posted on sign and on tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign posted at entrance to location			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on signs.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment piping and Kimray valve leaning against fence by Bellino #3 well. See photo.			
Corrective Action:	Remove unused equipment per Rule 603.f.			Date: 11/09/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Cattle panels around separators and meter houses.			
Corrective Action:				Date:
Type	LOCATION			
Comment:	Barbed wire fence around location.			
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:	Cattle panels around production tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and pumpjack.			
Corrective Action:				Date:

Equipment:			corrective date
Type: Pump Jack	# 2		
Comment:	Standard pumpjacks.		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	On separator stacks.		
Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:	2-3" flowlines from wellheads to separators. 2-2" flowlines from separator blowdown to produced water tank. 2-2" flowlines from separator dump valves to produced water tank and also to offsite produced water gathering system. 2-3" flowlines from separators to meter houses. 2-4" flowlines from meter houses to offsite doglegs.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellheads with block valves assemblies installed.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric VFD motors with MCC installed on pumping units.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Inspected Facilities									
Facility ID:	270	Type:	WELL	API Number:	067-09492	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			
Facility ID:	215369	Type:	WELL	API Number:	067-06974	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass	Culverts	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905640	Unused equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961720
687905641	Overview photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961721