

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2019

Submitted Date:

10/09/2019

Document Number:

687905634**FIELD INSPECTION FORM**

Loc ID 306798 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267024	WELL	SI	12/01/2017	GW	067-08790	LUNT 19-01 2	SI

General Comment:

Site inspection and equipment inventory with photos at the end of this report. Witnessed MIT for SI well status. Well has been in SI status since December/2017

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road through subdivision.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Labels/placards posted on tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Cattle panels around separator and meter house.			
Corrective Action:				Date:
Type	TANK BATTERY			
Comment:	Cattle panels around tank.			
Corrective Action:				Date:
Equipment:				
Type: Flow Line	# 5			corrective date
Comment:	1-3" flowline from wellhead to separator. 1-2" flowline from separator blowdown to produced water tank. 1-2" flowline from separator dump valve to produced water tank and also to offsite produced water gathering system. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 267024 Type: WELL API Number: 067-08790 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

-Last reported production in November/2017.
-Well was changed to SI status in December/2017.

-MIT Conducted with the following information:

-Start test pressure @380psi

-5min @ 380psi

-10min @ 380psi

-15min @ 380psi

-Final @ 380psi

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Gradient Terraces	Pass	Gravel	Pass			
Gravel	Pass					
Compaction	Pass	Culverts	Pass			
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905635	Overview photo.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961717
687905636	MIT chart recorder pressure.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4961718