

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402193878

Date Received:
10/01/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 27742

Name of Operator: EOG RESOURCES INC

Address: 600 17TH ST STE 1100N

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Kristen Limongelli

3032629931

kristen_limongelli@eogresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696101221

Inspection Date: 08/08/2019

FIR Submit Date: 08/19/2019

FIR Status: _____

Inspected Operator Information:

Company Name: EOG RESOURCES INC

Company Number: 27742

Address: 600 17TH ST STE 1100N

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 415149

Location Name: SIMBA Number: 1-06 County: _____

Qtrqtr: NWNE Sec: 6 Twp: 11N Range: 62W Meridian: 6

Latitude: 40.955631 Longitude: -104.362244

FACILITY - API Number: 05-123-00 Facility ID: 415149

Facility Name: SIMBA Number: 1-06

Qtrqtr: NWNE Sec: 6 Twp: 11N Range: 62W Meridian: 6

Latitude: 40.955631 Longitude: -104.362244

CORRECTIVE ACTIONS:

1 ☒ CA# 129356

Corrective Action:

Date: 09/10/2018

mission Control Device.
Controls produced oil & H2O tanks VOCs. ECD appears to not be operating. Pilot supply gas valve was shut, pilot electronic ignition was in off position. Inlet lines to ECD from tanks are open. These mechanical conditions need addressed to prevent unauthorized venting conditions. Mechanical Conditions.
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Original Corrective Actions date: 09/10/2018. Remains applicable.

This insp:

* ECD remains non operational. Observed pilot gas supply valve remaining shut.
See photos #15, 16.

Response: CA COMPLETED

Date of Completion: 09/20/2019

Operator
Comment:

See attached photos of combustor removal for the referenced location.

COGCC Decision: Approved via an AMI

COGCC
Representative:

Follow-up AMI Field Inspection Report Doc #696101408, dated 10/11/2019 confirms that ECD has been removed from location. Photos provided by Operator.
Corrective Action appears addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached photos of combustor removal for the referenced location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kristen Limongelli

Signed:

Title: Regulatory Administrator

Date: 10/1/2019 8:07:16 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402193878	FIR RESOLUTION SUBMITTED
402193879	location photo 1
402193880	location photo 2
402193882	location photo 3

Total Attach: 4 Files