

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/22/2019

Submitted Date:

10/06/2019

Document Number:

688305935

FIELD INSPECTION FORM

Loc ID 317086 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76830
Name of Operator: SCHMID PROPERTIES INC
Address: PO BOX 389
City: HICO State: TX Zip: 76457

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schmid, William	337-261-1500	tenniswilliam123@cs.com	
Sutphin, Dirk		dirk.sutphin@state.co.us	COGCC Engineer
Walker, Carolyn	254-796-2100	schmidprop@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236022	WELL	PR	11/06/1992	OW	121-08512	CLARK 10-35	PR

General Comment:

Reinspection

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 377-261-1500 and 970-554-1988 (check that all emergency contact numbers are current)

Corrective Action: Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at wellhead and under pump jack (see attached photos). Manifest waste for disposal.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 10/03/2018

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No _____

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	wire panels		
Corrective Action:		Date:	

Equipment:

Type	#				corrective date
Prime Mover	# 1				
Comment:	gas, propane				
Corrective Action:				Date:	
Pump Jack	#				
Comment:					
Corrective Action:				Date:	
Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

		CENTRALIZED BATTERY			
Comment:					
Corrective Action:				Date:	
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities

Facility ID: 236022 Type: WELL API Number: 121-08512 Status: PR Insp. Status: PR

Producing Well

Comment: [PR. Jun 2019 production reported to COGCC database. There is a gap in reported production between Jun 2008 and Mar 2012-contact COGCC Engineering.](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Pumper was contacted on 9/24/2019 about engine stained soil and said that location was cleaned up at the time of the cut, cap and cover of the Clark 2-35 PA on or around 10/1/2019. Inspector will reinspect for stained soil.	ShermaSe	10/06/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402200882	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956157
688305958	Schmid Properties Clark 10-35	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4956151