

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/07/2019

Submitted Date:

10/07/2019

Document Number:

697500642**FIELD INSPECTION FORM**

Loc ID 447778 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                        | Comment                         |
|--------------|-------|------------------------------|---------------------------------|
| ,            |       | wellinspections@bayswater.us | <a href="#">ALL INSPECTIONS</a> |

**Inspected Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num | Facility Name     | Insp Status |
|-------------|----------|--------|-------------|------------|---------|-------------------|-------------|
| 447778      | LOCATION | AC     |             |            | -       | Thornton 28-H Pad | RI          |

**General Comment:**[This is a Stormwater Inspection.](#)

| Inspected Facilities |        |       |          |             |   |         |    |               |    |
|----------------------|--------|-------|----------|-------------|---|---------|----|---------------|----|
| Facility ID:         | 447778 | Type: | LOCATION | API Number: | - | Status: | AC | Insp. Status: | RI |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Two \(2\) port-o-lets have fell over. Refer to the attached inspection photos.](#)

Corrective Action: [Per Rule 1002.f., immediately clean up area and properly secure all port-o-lets.](#)

Date: 10/07/2019

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402201954    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957217">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957217</a> |
| 697500643    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957209">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4957209</a> |