

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Sound walls		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 446017 Type: WELL API Number: 001-09946 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Liberty oil field services Stimulation Type: HYDRAULIC FRAC
 Other: _____

Observation:

Maximum Casing Recorded: 8638 PSI Tubing: _____
 Surface: _____ Intermediate: _____
 Production: _____ Instantaneous Shut-In Pressure (ISIP) _____
 Bradenhead Psi: 0 Frac Flow Back: Fluid: _____ Gas: _____

Comment: At time of inspection company was fracing two well at the same time. Fluid split at the missile .

Corrective Action: _____ Date: _____

Facility ID: 446021 Type: WELL API Number: 001-09950 Status: DG Insp. Status: DG

Well Stimulation

Stimulation Company: Liberty Oil field services Stimulation Type: HYDRAULIC FRAC
 Other: _____

Observation:

Maximum Casing Recorded: 7425 PSI Tubing: _____
 Surface: _____ Intermediate: _____
 Production: _____ Instantaneous Shut-In Pressure (ISIP) _____
 Bradenhead Psi: 0 Frac Flow Back: Fluid: _____ Gas: _____

Comment: At time of inspection company was fracing two well at the same time. Fluid split at the missile .

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Routine inspection. Weather clear and location dry.</u>	silverr	10/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501623	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4962115