

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2019

Submitted Date:

10/14/2019

Document Number:

699700036**FIELD INSPECTION FORM**

Loc ID 316373	Inspector Name: Heil, John	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 4 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>100264</u> Name of Operator: <u>XTO ENERGY INC</u> Address: <u>110 W 7TH STREET</u> City: <u>FORTH WORTH</u> State: <u>TX</u> Zip: <u>76102</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Moran, Rick		rick.moran@state.co.us	
Steiner, Nataalie	9706754089	natalie_steiner@xtoenergy.com	Spills
Murray, Richard		g.richard.murray@state.co.us	
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270456	WELL	PR	07/01/2019	GW	103-10401	YELLOW CREEK FEDERAL 3-45-1	EI
441025	SPILL OR RELEASE	CL	03/06/2015		-	SPILL/RELEASE POINT	EI

General Comment:

On September 25, 2019, COGCC Environmental Staff (John Heil) and COGCC Integrity Specialist (Richard Murray) conducted a field inspection of XTO ENERGY INC (XTO operator #100264) Location ID 316373 Yellow Creek Federal, Spill ID 468668. Natalie Steiner and XTO operational personnel were also onsite during the inspection. Weather was sunny and temperatures about 65 degrees Fahrenheit.

On September 24, 2019 COGCC Field Inspector Rick Moran observed water flowing down the location lease road and bubbling coming up from the ground near the pig station (Doc# 679705559). XTO was alerted of the release and was able to stop the leak. See Spill ID 468668 for more information on the release.

Inspected Facilities								
Facility ID:	270456	Type:	WELL	API Number: 103-10401	Status:	PR	Insp. Status:	EI
Facility ID:	441025	Type:	SPILL OR	API Number: -	Status:	CL	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 19

Comment: COGCC staff observed a 25 feet by 10 feet by 5 feet deep excavation on the south west side of the location. The excavation contained a 4-inch produced water line and a 6-inch gas line. The 4-inch produced water line had repaired section from when the location was owned by the previous operator (BOPCO LP). The black material in the bottom of the excavation is bedding for the flowlines. Upon inspection, the operator had removed the impacted soil from the access road ditch. COGCC staff observed moist soil in a sediment trap located east of the excavation and across the access road. The Operator stock piled the contaminated soil on a tarp northwest of the excavation. See photos and Spill ID 468668.

Corrective Action:

Date:

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment:

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700044	20190925 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4962212