

APACHE CANYON 14-01 API# 05-071-06130 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901233



Photo 1: There was no erosion found up gradient of the culvert inlet. It appears that the established vegetation up gradient of the bar ditch was disturbed during the previous maintenance efforts. The sediment in the bar ditch is believed to have come from the earth disturbance. To correct this, the accumulated sediment was removed from the bar ditch. The disturbed soil was hand broadcast with an approved CPW seed mix to promote the establishment of vegetation. Erosion control blankets were installed for sediment control.

APACHE CANYON 14-01 API# 05-071-06130 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901233



Photo 2: A bell hole was created below the culvert inlet to allow sediment time to drop out before entering the culvert inlet.

APACHE CANYON 14-01 API# 05-071-06130 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 - DATE: OCTOBER 14, 2019
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 689901233



Photo 3: The sediment was removed from the culvert inlet.