

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/08/2019

Submitted Date:

10/08/2019

Document Number:

699500174

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
317813 MEDINA, JUSTIN 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240010	WELL	PA	09/18/2014	OW	123-07798	ROCKY MTN FUEL CO "F" 2	PA
416096	WELL	SI	12/01/2018	GW	123-31263	NRC 23-9	SI
416098	WELL	PA	06/05/2019	OW	123-31265	NRC 36-9	PA
416102	WELL	SI	12/01/2018	OW	123-31269	NRC 35-9	SI
416119	WELL	SI	12/01/2018	GW	123-31284	NRC 13-9	SI
416252	WELL	PA	02/15/2019	OW	123-31316	NRC 14-9	PA
416385	WELL	SI	12/01/2018	OW	123-31356	NRC 11-9	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

4

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

4

Comment: Automation

Corrective Action:

Date:

Type: Plunger Lift

4

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 240010 Type: WELL API Number: 123-07798 Status: PA Insp. Status: PAFacility ID: 416096 Type: WELL API Number: 123-31263 Status: SI Insp. Status: SIFacility ID: 416098 Type: WELL API Number: 123-31265 Status: PA Insp. Status: PAFacility ID: 416102 Type: WELL API Number: 123-31269 Status: SI Insp. Status: SIFacility ID: 416119 Type: WELL API Number: 123-31284 Status: SI Insp. Status: SIFacility ID: 416252 Type: WELL API Number: 123-31316 Status: PA Insp. Status: PAFacility ID: 416385 Type: WELL API Number: 123-31356 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules.	medinaj	10/08/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500175	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4962830