

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
	Comment: Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
	Comment: Steel rod		
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Bradenhead	# 1				
Comment:	Appears to be plumbed to surface				
Corrective Action:		Date:			
Type: Plunger Lift	# 1				
Comment:					
Corrective Action:		Date:			

Venting:

Yes/No	NO		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Flaring:

Type			
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 256950 Type: WELL API Number: 123-19942 Status: TA Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Well is shut in and flowline valves are LOTO off well head. Well has been shut in and TA Since April of 2017. Well has produced 3MCF in December of 2018. Well has been TA/SI for a extended period of time please provide future plans for utilization per rule 3190b (3)

Corrective Action: Date:

COGCC Comments

Comment	User	Date
This is a follow up inspection per Doc#693501305. All corrective actions appear to have been addressed at time of inspection.	silverr	10/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501633	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963096