

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2019

Submitted Date:

10/15/2019

Document Number:

687905654**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
333515 \_\_\_\_\_ Stewart, Joseph \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10679  
Name of Operator: LOGOS OPERATING LLC  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87415

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	<a href="#">SW Inspection Reports.</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216530	WELL	PR	11/27/1998	GW	067-08136	BONDAD 33-9 31A	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road access through locked gate.		
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Labels/placards posted on sign on fence at produced water tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign posted on fence at produced water tank.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact information posted on signs.		Date: _____
Corrective Action:			
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 6		
Comment:	1-2" flowline from wellhead to separator. 1-1" flowline from separator dump valve to produced water tank. 1-2" flowline from separator to compressor suction. 1-2" flowline from compressor discharge to dehydrator. 1-1" flowline from dehydrator dump valve to produced water tank. 1-2" flowline from dehydrator to offsite dogleg.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Sound panels around compressor.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	

Type: Bird Protectors	# 2	
Comment:	One dehydrator stack. One on separator.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Wellhead with block valve assembly installed.	
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV STEEL		
Comment:	125bbl tank with expanded metal screen.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 216530 Type: WELL API Number: 067-08136 Status: PR Insp. Status: PR

**Producing Well**

Comment: [producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for compressor oil tank.
Gravel	Pass					
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for dehydrator glycol pump.
Gradient Terraces	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905655	Overview photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963569">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963569</a>