

Inspection Photos
Location Name: Edkam #2-23
Location ID: 332669



Photo 1 TNK BTRY 300 BBL crude oil tank does not have floodplain anchors. Produced water tank does have anchors.



Photo 2 TNK BTRY 300 BBL crude oil tank does not have floodplain anchors. Produced water tank does have anchors.

Inspection Photos
Location Name: Edkam #2-23
Location ID: 332669



Photo 3 Maps clearly show well head and TNK BTRY are in floodplain.



Photo 4 WH Well is SI

Inspection Photos
Location Name: Edkam #2-23
Location ID: 332669



Photo 5 Sep/meter house and ECD. HOZ Sep has floodplain anchors



Photo 6 flow line valves are closed off well head