

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2019

Submitted Date:

10/15/2019

Document Number:

694500142**FIELD INSPECTION FORM**Loc ID 316766 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10490Name of Operator: ENERGY QUEST II LLCAddress: 4526 RESEARCH FOREST DR #200City: THE WOODLANDS State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------|---------|
| jeff teare | | jeff.teare@energyquest.us | |
| Booco, Randy | | boocosinc@aol.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 113016 | PIT | AC | | | - | PEOC - NVG 41-23H | EI |
| 232758 | WELL | PR | 02/09/1991 | OW | 107-06173 | PEOC-NVG 41-23H | EI |

General Comment:

On 8/5/2019 COGCC staff, Kris Neidel inspected the PEOC-NVG 41-23H. and pit facility id 113016. Weather was mostly clear and 75 degrees. This inspection address specific Environmental items documented here and does not necessary address previous required action required. The pit has been closed sometime in the past. The well was SI at the time of inspection. It appeared that the emission control device on location was SI at the time of inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐

| Spills: | | | | | |
|--|-----------|----------|-------|------------|--|
| Type | Area | Volume | | | |
| Crude Oil | WELLHEAD | <= 1 bbl | | | |
| Comment: wellhead is oily | | | | | |
| Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | | | Date: | 10/30/2019 | |
| Crude Oil | Flow Line | <= 1 bbl | | | |
| Comment: oily soil near wellhead on flowlines | | | | | |
| Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | | | Date: | 10/30/2019 | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 113016 Type: PIT API Number: - Status: AC Insp. Status: EIFacility ID: 232758 Type: WELL API Number: 107-06173 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694500145 | photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963684 |