

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2019

Submitted Date:

10/15/2019

Document Number:

696101414

**FIELD INSPECTION FORM**

Loc ID 305204 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10071  
Name of Operator: HIGHPOINT OPERATING CORPORATION  
Address: 555 17TH ST STE 3700  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
James, Brian		bjames@hpres.com	<a href="#">All Inspections</a>
Brown, Tim		tbrown@hpres.com	<a href="#">MIT</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275567	WELL	TA	10/01/2018	GW	123-22642	ROTHER 23-31	TA

**General Comment:**

[This is a MECHANICAL INTEGRITY TEST | MIT inspection](#)  
[Well: Temporarily Abandoned | TA.](#)

**Inspected Facilities**

Facility ID: 275567 Type: WELL API Number: 123-22642 Status: TA Insp. Status: TA

**Workover**

Comment: Mechanical Integrity Test | MIT to maintain Shut-In/Temporarily Abandoned | SI/TA status.

Tbg Depth: 6299' ; CIBP@6390'. ITP @ 43 psig, ICP @ 43 psig, Bradenhead @ 0 psig, pressure Csg to 407 psig and isolate wellbore from pump,  
5 minute: Tbg @ 43 psig, Csg @ 404 psig, Bradenhead @ 0 psig  
10 minute: Tbg @ 43 psig, Csg @ 402 psig, Bradenhead @ 0 psig  
15 minute: Tbg @ 43 psig, Csg @ 402 psig, Bradenhead @ 0 psig  
Release pressure, SIW, RDMO.  
Loss / Gain: -5 psig.

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments
----------------

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 10/15/2019 at approximately 11:41 hrs. I, Bret Evins, conducted an on-site inspection at:                      Operator Name: HIGHPOINT OPERATING CORPORATION                      Location Name: ROTHE-65N63W /31NESW                      Location ID: 305204                      Well Name: Rothe 23-31                      API: 05-123-22642                      Location County: Weld County, Colorado                      Weather: Damp from prior rain / snow.</p> <p>While there, I observed:                      Well(s): 1 ; Temporarily Abandoned   TA.                      Witnessed Mechanical Integrity Test   MIT to maintain Shut-In/Temporarily Abandoned   SI/TA status.                      Observed MIT recording on pump truck computer.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/15/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101418	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963772">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963772</a>
696101419	MIT - Pressure chart	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963773">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963773</a>