

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402203804

Date Received:
10/09/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

ronaldmack@tcenergyllc.com

robfoos@tcenergyllc.com

ediefitzgerald@tcenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689901228

Inspection Date: 09/12/2019

FIR Submit Date: 09/13/2019

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 307376

Location Name: APACHE CANYON-634S67W Number: 17SWSW County: LAS ANIMAS

Qtrqr: SWS Sec: 17 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.080394 Longitude: -104.917585

FACILITY - API Number: 05-071- -00 Facility ID: 217563

Facility Name: APACHE CANYON Number: 17-13

Qtrqr: SWS Sec: 17 Twp: 34S Range: 67W Meridian: 6
W

Latitude: 37.080394 Longitude: -104.917585

CORRECTIVE ACTIONS:

1 ☒ CA# 130555

Corrective Action: Install or repair required BMPs per Rule 1002.f.
BMP's shall be implemented in accordance to good engineering practice.

Date: 08/23/2019

Response: CA COMPLETED

Date of Completion: 10/07/2019

Operator Comment: The rock check dams were removed from the bar ditch. (2) new culverts were installed to reduce the amount of run off the bar ditch would receive. Rock socks were installed in the bar ditch to filter sediment. Erosion control blankets were installed to stabilize the disturbed soil. A sediment trap was installed at the beginning of the water call out to drop out sediment Turf reinforcement mats were installed for erosion control. Rip rap was installed in the bar ditch to dissipate energy. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed:

Title: SR. Environmental Tech.

Date: 10/9/2019 8:03:21 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402203804	FIR RESOLUTION SUBMITTED
402203809	Photo Log

Total Attach: 2 Files