

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/15/2019

Submitted Date:

10/15/2019

Document Number:

696101413

FIELD INSPECTION FORM

Loc ID 419018 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Tim Brown		tbrown@hpres.com	MIT
James, Brian		bjames@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419013	WELL	TA	08/03/2017	GW	123-32101	ROTHER 44-30	TA

General Comment:

[This is a MECHANICAL INTEGRITY TEST | MIT inspection](#)
[Well: Temporarily Abandoned | TA](#)
[Reference: Form 42 Doc #402186982.](#)

Inspected Facilities

Facility ID: 419013 Type: WELL API Number: 123-32101 Status: TA Insp. Status: TA

Workover

Comment: Mechanical Integrity Test | MIT to maintain Shut-In/Temporarily Abandoned | SI/TA status

Tbg Depth: 6110' ; CIBP@6208' ITP @ 0 psig, ICP @ 0 psig, Bradenhead @ 0 psig,
pressure Csg to 357 psig and isolate wellbore from pump,
5 minute: Tbg @ 0 psig, Csg @ 356 psig, Bradenhead @ 0 psig
10 minute: Tbg @ 0 psig, Csg @ 356 psig, Bradenhead @ 0 psig
15 minute: Tbg @ 0 psig, Csg @ 356 psig, Bradenhead @ 0 psig
Release pressure, SIW, RDMO.
Loss / Gain: -1 psig.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 10/15/2019 at approximately 11:03 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: Roth /44-30 Location ID: 419018 Well Name: Rothe 44-30 API: 05-123-32101 Location County: Weld County, Colorado Weather: Damp from prior rain / snow.</p> <p>While there, I observed: Well(s): 1 ; Temporarily Abandoned TA. Witnessed Mechanical Integrity Test MIT to maintain Shut-In/Temporarily Abandoned SI/TA status. Observed MIT recording on pump truck computer.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/15/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101413	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963776
696101416	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963770
696101417	MIT - Pressure chart	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4963771